



NOTES:

1. TIP 120 is a Darlington transistor with an internal recirculating diode.
2. Make certain that the polarity of each capacitor is wired correctly.

vb_stepper_motor1